



UKATA Duty To Manage Asbestos Training Course



Call us: 01422 358184

Visit us: www.bosstraining.co.uk

UKATA Duty To Manage Asbestos

The duty to manage asbestos is directed at those who manage non-domestic premises: the people with responsibility for protecting others who work in such premises, or use them in other ways, from the risks to ill health that exposure to asbestos causes.

Who should attend?

Any persons who requires an overview of the duty to manage and legislative requirements. This would normally include, but is not limited to duty holder's assistants, appointed persons assistants, building owners, landlords, sub-lessors, managing agents etc. and any person assisting duty holders in the compliance with CAR 2012 regulation 4.

Course Content:

- Air tests: 4 stage clearance, licenses accreditation and their meaning
- Surveyor competence
- Sampling
- Risk Assessments: priority and material assessment algorithms.
- 8 steps to developing an asbestos management plan
- Management options for asbestos containing materials
- Safe systems of Work; training of staff: monitoring contractors, removal companies, surveyors and laboratories
- Emergency procedures
- The properties of asbestos and its effects on health
- The types uses and likely occurrence of asbestos in buildings and plant
- Current legislation and guidance relating to asbestos
- Licensed and Non-Licensed work and what is the difference?
- Safe removal and repair of asbestos
- Competence assessment of employees and sub-contractors
- Asbestos Surveys: planning, reporting, registers

Course Duration:

Full day including Ukata Asbestos Awareness unless this has been completed within 6 months of the course.

Ask also about PASMA and IPAF Courses





Training available across the UK at your premises or at one of our Training Centre's

Booking with BOSS could not be simpler...

...Just one phone call and BOSS will take care of the rest.

Or Email: enquiries@bosstraining.co.uk

Call us: 01422 358184

Visit us: www.bosstraining.co.uk